Research and Implementation of Integrated Methods of Unsupported Printing and Five-Axis CNC Machining Technology

HaiGuang ZHANG, ZeFeng SUN, QingXi HU, Herfried LAMMER

Abstract: In traditional 3D printing, the best method for creating overhanging structures is to add supporting materials; however, this often leads to an increase in costs and a decrease in printing efficiency. Therefore, a five-axis CNC machining technology is introduced in this paper, proposing an unsupported 3D printing method. Models requiring support structures were supported by an existing supporting surface by adding two degrees of freedom (rotation and swinging). Moreover, effectiveness of the proposed method was verified by experiment.

Keywords: CNC technology; supporting structures; 3D printing

1 INTRODUCTION

In recent years, advances in rapid manufacturing technologies, in particular additive manufacturing (AM), have greatly shortened the development cycle of new products, thereby improving the efficiency and flexibility of producing new products [1-3]. The AM process is particularly well-suited to complex three-dimensional (3D) structures, however, some models containing suspension, hollow, or other complicated structures often need additional support structures to ensure smooth printing. The addition of support structures slows down the speed of fabrication and can introduce artifacts onto the finished surface, which can damage the actual product upon removing the supporting material [4-7].

In recent years, more attention has been paid to the optimization of support structures, and to reducing, optimizing, and even removing these structures altogether, which has become an important goal of 3D printing research. In this light, Wu et al. [6] proposed a self-supporting rhombic filling method for 3D printing and demonstrated its effectiveness in generating interior designs for applications that require improvements in mechanical stiffness and static stability. Mirzendehdel et

al. [8] found that topology optimization often leads to designs that are not AM friendly, therefore the concept of "support structure topology sensitivity" was introduced, combined with performance sensitivity, and a topology optimization framework was built to maximize performance. Furthermore, Hu et al. [9] presented an orientation-driven shape optimizer to slim down support structures, which can be employed as a tool to help designers optimize the original model, thereby achieving a more self-supported shape. Additionally, Thrimurthulu et al. [10] proposed a multi-standard genetic algorithm that improves surface quality, reduces the amount of support structure required, and decreases overall construction time. Tool path planning methods for sculptured surfaces machining include iso-parametric, iso-planar, and isoscallop methods [15]. Lee et al. [16] proposed a nonisoparametric tool path planning method, which uses all the right-side end points of the previous tool path as left-side end points of the current path. Xu et al. [22] introduced a dual drive curve tool path planning method and results demonstrated effective elimination of sharp scallops between adjacent tool paths, thereby maintaining a smooth tool path and improving the quality of machined surfaces.



Figure 1 Representative 3D model: (a) STL model and (b) model slicing

In summary, research to date has mainly focused on the optimization of support structures, whereas real unsupported printing has not yet been realized. The algorithms for optimizing support structures require a large amount of calculations and are difficult to apply to actual printing. Therefore, in this paper, the concept of '5-axis CNC technology' is introduced, and proposes an unsupported 3D printing method, which realizes the 3D printing process without any support materials.

2 OVERVIEW OF NO-SUPPORT CNC3D PRINTING STRATEGY

In 3D printing systems, new products are usually developed using computer-aided design (CAD) software,

such as Catia and Solidworks [12]. Designs are then exported to a standard data model, such as STL, which is imported into slicing software to generate G-code based on horizontal slicing [12, 13]. A representative 3D printing model is shown in Fig. 1.

As shown in Fig. 1(b), the overhanging part of the part requires supporting materials, which will greatly increase printing time and material costs. Therefore, five-axis CNC machining technology is proposed to realize five-axis 3D printing by adding two degrees of freedom of rotation and swinging, and printed materials can be used as the substrate by utilizing the space motion of the platform. This avoids the addition of supporting materials thus minimizing printing times and reducing costs. The no-support CNC 3D printing process, shown in Fig. 2, includes the STL input, model partitioning, model rotating, model slicing, path transformation, and finally, printing.



Figure 2 No-support CNC 3D printing process

(1) Model Input

Two formats can be used for STL files: ASCII format or binary [18, 19].

(2) Model partitioning

To perform model partitioning, geometric characteristics of the model should be analyzed to judge whether the model requires support structures during the printing process. If there is no requirement for support material, traditional 3D printing can be used and a path is immediately generated to print the model. If the model requires support material, a surface should be identified which can be used to divide model into multiple sub-parts. (3) Model rotation

The order of sub-part printing should be determined after the model has been divided, ensuring each sub-part does not need any material other than the sub-part itself during the printing process, thereby realizing unsupportive printing of the entire model. The sub-parts must also be rotated by an appropriate angle prior to slicing to support substrate transitions.

(4) Model slicing

Each sub-part is sliced by existing open-source slicing software, such as Cura or Slic3r.

(5) Path transformation

In the model, each sub-part will be rotated by a specific angle to support some certain parts. The coordinate will be changed after the rotation, and therefore it needs to be calculated through path transformation to ensure the accuracy of each sub-part.

3 NO-SUPPORT CNC 3D PRINTING METHOD 3.1 Model Partitioning

The STL models that require additional support material usually have sudden changes in cross-sectional area. The sudden change is due to a large difference in the areas of two adjacent sections of the part, and therefore, model partitioning is required.

In model partitioning, three directions, X, Y, and Zmust be traversed. The X direction is taken as an example to illustrate the partitioning process. First, the thickness of each slice is set as d, and the cross-sectional area of Surface(i) and Surface(i + 1) are calculated, which are two adjacent sections after cutting. The area of Surface(i) is S_{sup} and the area of Surface(i + 1) is S_{sub} . Next, the sectional area coefficient ∂ of the section is set. A large number of experiments have shown that the angle between one side of the object (L1) and vertical line (L2) is greater than 45° and dangling [14, 20], and collapse will occur without a base. Assuming Surface(i + 1) is greater than Surface(i), the difference in length between Surface(i + 1) and Surface(i)is Line (L3). Since the angle is 45°, Line (L3) and Line (L4) have the same length, therefore, the area coefficient ∂ can be derived and the formula is

$$\partial = \frac{Surface(i+1) - Surface(i)}{d} \tag{1}$$

where *i* is the slice number and $i \ge 1$.

When $\partial > 1$, the model must be split, and the distance from the origin is $i \times d$. When *Surface*(i + 1) is greater than *Surface*(i), ∂ is greater than -1, and needs to be divided. The derivation of sectional area coefficient ∂ is shown in Fig. 4.

As shown in Fig. 3(b), when the model is divided Surface 1 and Surface 2 are called the partition surfaces.



3.1.1 Cross-Sectional Area

The model is divided based on whether there is a sudden change in area. The specific calculation process is shown in Fig. 5.



Figure 5 Process to determine model sectional area

(1) Input STL model and traverse *X*, *Y*, *Z* directions of the model.

(2) Judge whether the model has hole structures.

Take a point on the cross-section of the polygon, generally selected as the lower right corner of the polygon, and starting from this point, make a ray to the positive direction of the *X*-axis. Calculate the number of intersection points between the ray and polygon. When the number of intersection points is zero or an even number, the polygon is the outer contour. When the number of intersection points is odd, the polygon is the inner contour; in other words, it has a hole structure.

(3) If the part has hollow structures, it should be transformed into monotonous polygons. If there are no any hollow structures, it will be directly triangulated.

If the cross section is identified as having hole structures, it must be transformed into a monotonous polygon. Set the vertex of the outer contour in accordance with the anti-clockwise order and set the vertex of the inner contour in accordance with the clockwise order. The feature point on the inner contour refers to the vertex where the coordinate value Y is the largest and the coordinate value X is relatively small, among all vertices of the inner contour. The specific steps are as follows:

Step 1: Traverse the vertices of the inner contour to find the characteristic points.

Step 2: Find the point closest to the inner contour feature point among the vertices of the outer contour.

Step 3: Join the feature point to the point closest to the inner contour feature point, so that the inner contour and outer contour forms a polygon.

The transformation process of monotonous polygons is shown in Fig. 6. Point V_9 is the characteristic point on the inner contour and Point V_1 is the point on the outer

contour closest to V_9 . Joining the inner contour point V_9 and outer contour point V_1 , this becomes a monotone Polygon.



(4) Monotonous Polygon Triangulation

The method of monotonous polygon triangulation requires taking out three points conforming to the conditions in the positive direction of the trajectory and repeating the process until the remaining polygons are triangles. Finally, the areas of all triangles are accumulated.

The monotonous polygon triangulation method is shown in Fig. 7, where n is the number of polygon vertices. Supposing there are three consecutive vertices, V_i , V_{i+1} , and V_{i+2} , on the polygon, the condition required for V_{i+1} to be the convex vertex is

$$\xrightarrow{V_i V_{i+1}} \xrightarrow{V_{i+1} V_{i+2}} >0$$
 (2)

The polygon triangulation algorithm requires inputting the polygon vertex set $S = \{V_1, V_2, V_3, ..., V_n\}$ and performing the following steps:

Step 1: Calculate n. If n = 3, the polygon is a triangle, go to Step 6. Otherwise, go to Step 2;

Step 2: Obtain the three continuous vertices, V_i , V_{i+1} , and V_{i+2} , from set S and calculate whether the vertex is the convex vertex according to Eq. (2). If yes, go to Step 3. Otherwise, go to Step 4;

Step 3: Calculate whether the remaining polygons intersect edge V_iV_{i+2} except the edges V_iV_{i+1} and $V_{i+1}V_{i+2}$. If yes, go to Step 4. Otherwise, go to Step 5;

Step 4: If the three vertices, V_i , V_{i+1} , and V_{i+2} , cannot form a triangle, i = i + 1, and go to Step 2;

Step 5: A new triangle is formed by three vertices, V_i , V_{i+1} , and V_{i+2} . Remove the triangle and sort the remaining vertices, n = n - 1, and go to Step 1;

Step 6: End.

A representative example of using the algorithm is shown in Fig. 8(a). Since vertex V_2 of the triangle $V_1V_2V_3$ is convex, the method proceeds to Step 5. After triangle $V_1V_2V_3$ is removed, the vertices are sorted again. As shown in Fig. 8(b), the edge L1 of the triangle $V_1V_2V_3$ intersects with the edge $V_{11}V_{12}$. Therefore, the triangle $V_1 V_2 V_3$ cannot form a polygon, i = i + 1, and the method proceeds to Step 2. Vertex V_3 of triangle $V_2V_3V_4$ is convex and no edge intersects with V_2V_4 , so the algorithm proceeds to Step 5, and so on. The result is shown in Fig. 8(c). Then, Fig. 8(d) and Fig. 8(e) can be calculated. When n = 3, the process of monotonous polygon triangulation ends. An example result is shown in Fig. 8(f).







Figure 8 Representative example of the polygon triangulation process

(5) The cross-sectional area is calculated by overlaying the triangles in the polygons.

Then, the cross-sectional area can be obtained by summing all the areas of the triangles. The formula for the area of a triangle is

$$S = \sqrt{p(p-a)(p-b)(p-c)}$$
(3)

where $p = \frac{1}{2}(a+b+c)$, and *a*, *b*, and *c* are the side lengths of the triangle.

The cross-sectional area can be calculated as

$$S_{All} = \sum_{1}^{n} S_1 + S_2 + S_3 + \dots + S_n \tag{4}$$

where n is the number of triangles.

3.2 Determining the Model Printing Sequence

Different subsections will have different priorities. The underlying material, or other material supporting printing, is called the supporting foundation. Therefore, the supporting foundation is a relative concept. The specific process is as follows:

First of all, among all sub-parts serving as the basis of support, the sub-part that can be supported without requiring any other sub-parts and has a larger volume is regarded as the highest priority sub-part, i.e., the sub-part that must be printed first. The sub-parts that need a supporting foundation while also supporting other subsections are defined as sub-priority subsections. Thus, all sub-parts are printed correctly in the order of printing priority. The method for determining the order of printing of sub-parts is showed in Fig. 9.

The STL model shown in Fig. 1(a) is an example of a segmented model, as shown in Fig. 3(a). The angle between Section 1 and Section 2 is 90°, therefore, the parting Angle 1 is 90°. Then, a 90° rotation in the clockwise direction, Subsection 2 provides a supporting base for Subsection 1. After a 180° rotation, Section 2 provides a supporting base for Section 3. The actual printing sequence of the 3D model diagram is shown in Fig. 10.





3.3 Path Transformation

When the model is rotated and after slicing, the G-code needs to be reorganized. The conversion method of the printing path is as follows:

Step 1: After model partitioning is finished, the crosssectional center of gravity of the section is generated, denoted as (a_j, b_j, c_j) . As shown in Fig. 3(b), Point 1 is the center of gravity of Section 1. After rotation, the center of gravity is recorded as (a_{sm}, b_{sm}, c_{sm}) and the formula is

$$\begin{pmatrix} a_{sm} \\ b_{sm} \\ c_{sm} \end{pmatrix} \begin{pmatrix} n_x^2 (1 - \cos\theta) + \cos\theta & n_x n_y (1 - \cos\theta) + n_z \sin\theta \\ n_x n_y (1 - \cos\theta) - n_z \sin\theta & n_y^2 (1 - \cos\theta) + \cos\theta \\ n_x n_z (1 - \cos\theta) + n_y \cos\theta & n_z n_y (1 - \cos\theta) - n_x \sin\theta \end{pmatrix}$$

where θ is the angle of rotation and (n_x, n_y, n_z) is the vector in which the axis of rotation is located.



Figure 11 Visualized tool path sliced using the no-support CNC 3D printing method

Step 2: The slicing software after model partitioning is sliced on the bottom of the printing platform, therefore, it is necessary to recalculate the coordinates of the center of gravity of model section, denoted (a_f , b_f , c_f), and place (a_f , b_f , c_f) into the Eq. (5) to obtain the converted center of gravity coordinates, denoted (a_m , b_m , c_m).

Step 3: The translation of *XYZ* is Δa , Δb , and Δc , where $\Delta a = a_{sm} - a_m$, $\Delta b = b_{sm} - b_m$, $\Delta c = c_{sm} - c_m$. For example, G1 *Xx'*, *Yy'*, *Zz'*, E0.1is sliced by the slicing software and converted to G1 *X*(*x*' + Δa), *Y*(*y*' + Δb), *Z*(*z*' + Δc) E0.1.

Step 4: Since 3D printing is formed by continuous stacking of a material, the layer height is taken into account in the stacking direction (usually the *Z*-axis direction) in Step 3, and the G-code is converted to G1 $X(x' + \Delta a)$, Y(y')

$$\begin{array}{c} n_{x}n_{z}\left(1-\cos\theta\right)-n_{y}\sin\theta\\ n_{y}n_{z}\left(1-\cos\theta\right)+n_{x}\sin\theta\\ n_{z}^{2}\left(1-\cos\theta\right)+\cos\theta \end{array} \right) \begin{pmatrix} a_{j}\\ b_{j}\\ c_{j} \end{pmatrix}$$
(5)

+ Δb), and $Z(z' + \Delta c + 0.1)$ E0.1. The actual G-code simulation of the STL model is shown in Fig. 11.

4 EXPERIMENTAL PLATFORM AND EXPERIMENTAL VERIFICATION

4.1 Experimental Platform

As shown in Fig. 12(a), the device can be improved based on the X-Y transmission mechanism and equipped with a receiving platform. To ensure higher mechanical transmission stability and excellent mechanical properties, metal materials are used for the main printing platform and guide rail. The movement ranges of X, Y, and Z is 500 mm, 500 mm, and 700mm respectively. The movement angles of the A-axis and C-axis are both $\pm 360^{\circ}$. The receiving platform is circular with a diameter of 160 mm. The slave computer control system [19] consists of a six-axis control panel to realize individual control in five degrees of freedom, as shown in Fig. 12(b). The host computer control system was developed by QT5.8 and used to realize the Gcode conversion and calculation of the cross-sectional center of gravity.

4.2 Experimental Verification

In this experiment, the temperature of the nozzle was set to 210 °C with the ABS filament [22], and the temperature of the hot bed was set to 50 °C. The support fill density was 30%, the layer height was 0.2 mm, and the slow and fast print speeds were set to 40 mm/s and 60mm/s, respectively. The travel speed was set to 150 mm/s, the support overhang angle was 60°, and the nozzle diameter D was 0.4 mm.



Figure 12 Hardware and software platform: (a) X-Y structure of five-axis platform and (b) host computer control system



Figure 13 Parts printed using different slicing methods: (a) no-support CNC-3D and (b) traditional 3D printing

Table 1 Experimental results based on the STL model presented in Fig. 1			
Experimental results		0/ difference	
No-support CNC 3D printing method	Traditional printing method	% difference	
Printing time = 3128 s	Printing time = 6255 s	50%	
Material consumption = 3965 mm	Material consumption = 9934 mm	50%	

4.2.1 Example of a Simple Model

The X-Y structure of the five-axis platform, based on the G-code conversion of the model presented in Section 2.3, was used for printing. Images of the 3D-printed structures are shown in Fig. 13. A comparison of print time and print consumables is presented in Tab. 1 and shows the printing time of the STL model was reduced by 50% and consumables were reduced by nearly 60% (measured in mm) using the same slice parameters.

4.2.2 Example of Bracket Parts

As shown in Fig. 14, for mechanical bracket parts, the traditional 3D printing process requires a supporting structure regardless of changes in the print direction, which greatly increases printing time. The no-support CNC-3D printing method was also used, as shown in Fig. 15. Subsection 1 was first cut first along the *z*-axis direction, then Section 2 and Section 3 were cut along the *y*-axis direction. However, when Section 2 was printed, the aluminum block



of the heating module has a certain volume, and if the print head moves vertically, it will collide with the printed, as

shown in Fig. 17. Therefore, the A-axis and C-axis should

rotate at a certain angle, such that the print head in the

nozzle will not interfere with the printed part. When Angle

2 is 45°, according to the size of the model in Fig. 14,

calculating Angle1 is easy. The visualized tool path sliced using the no-support CNC-3D printing method is shown in

Fig. 16. In actual printing, the nozzle interferes with the

printed part, as shown in Fig. 18.

Figure 14 3D illustration of bracket part



Figure 16 Visualized tool path sliced using no-support CNC 3D printing method



Figure 17 Problems associated with vertical printing



Figure 18 No interference between nozzle and printed parts after rotation of the receiving platform

Table 2 Experimental results from STL model

Experimental results		% difference
No-support CNC 3D printing method	Traditional printing method	76 difference
Printing time = 11206 s	Printing time = 20632 s	45.7%
Material consumption = 17874 mm	Material consumption = 32344 mm	44.7%



Figure 19 Brackets printed using different slicing methods: (a) no-support CNC 3D printing and (b) traditional 3D printing

As shown in Tab. 2, the printing time was reduced by 45.7%, which greatly accelerates the printing speed and reduces material consumption by 44.7%. Actual printed objects generated using the no-support CNC 3D printing method and traditional printing method are shown in Fig. 19.

5 CONCLUSIONS AND FUTURE WORK

This paper introduces a five-axis CNC machining technology as an unsupported 3D printing method and provides a new method of printing complex hollow models. In contrast to traditional methods, the proposed method can be applied to actual printing without any complex calculations. The feasibility of the software and effectiveness of the no-support CNC 3D printing method was shown by experiment. The concept of '5-axis CNC technology' was implemented for fused deposition modeling (FDM), but can be extended to industrial production, mold manufacturing, aerospace, medical, and other fields, making it more convenient.

However, the no-support CNC 3D printing method does have some limitations. Collision between the receiving platform and nozzle often results in slight positional changes of the receiving platform, thereby reducing its accuracy. Furthermore, this method cannot be adapted to certain thin-shell curved surface models. Therefore, further work is needed to be able to apply the CNC cutting trajectory to these problems by incorporating current 3D print path formats.

Acknowledgements

This research was supported by funding from the Austrian-Chinese Cooperative R&D Projects and the Shanghai Key Laboratory of Intelligent Manufacturing and Robotics.

6 **REFERENCES**

- Yang, S. (2003). Trends in the development of advanced manufacturing technology. *Chinese Journal of Mechanical Engineering*, 39(10). https://doi.org/10.3901/JME.2003.10.073
- [2] Grguras, D. & Kramar, D. (2017). Optimization of Hybrid Manufacturing for Surface Quality, Material Consumption and Productivity Improvement. *Strojniski vestnik-Journal of Mechanical Engineering*, 63(10), 567-576. https://doi.org/10.5545/sv-jme.2017.4396
- [3] Ameen, W., Al-Ahmari, A., Mohammed, M.K., Abdulhameed, O., Umer, U., & Moiduddin, K. (2018). Design, finite element analysis (FEA), and fabrication of custom titanium alloy cranial implant using electron beam melting additive manufacturing. *Advances in Production Engineering & Management*, 13(3), 267-278. https://doi.org/10.14743/apem2018.3.289
- [4] Leary, M., Merli, L., Torti, F., Mazur, M., & Brandt, M. (2014). Optimal topology for additive manufacture: a method for enabling additive manufacture of support-free optimal structures. *Materials & Design*, 63, 678-690. https://doi.org/10.1016/j.matdes.2014.06.015
- [5] Dede, E. M., Joshi, S. N., & Zhou, F. (2015). Topology optimization, additive layer manufacturing, and experimental testing of an air-cooled heat sink. *Journal of Mechanical Design*, 137(11). https://doi.org/10.1115/1.4030989
- [6] Maute, K., Tkachuk, A., Wu, J., Qi, H. J., Ding, Z., & Dunn, M. L. (2015). Level set topology optimization of printed active composites. *Journal of Mechanical Design*, 137(11), 81-96. https://doi.org/10.1115/1.4030994
- [7] AIAA. (2014). Topology optimization for additive manufacturing: considering maximum overhang constraint. *AIAA Journal*, *27*(39), 12-12.
- [8] Mirzendehdel, A. M. & Suresh, K. (2016). Support structure constrained topology optimization for additive manufacturing. *Computer-Aided Design*, 81, 1-13. https://doi.org/10.1016/j.cad.2016.08.006
- [9] Kailun Hu, Shuo Jin, Charlie C. L. Wang. (2015). Support slimming for single material based additive manufacturing. *Butterworth-Heinemann*, 65, 1-10. https://doi.org/10.1016/j.cad.2015.03.001
- [10] Pandey, P. M., Thrimurthulu, K., & Venkata Reddy, N. (2004). Optimal part deposition orientation in FDM by using a multicriteria genetic algorithm. *International Journal of Production Research*, 42(19), 4069-4089. https://doi.org/10.1080/00207540410001708470
- [11] Zhao, H. M., He, Y., Fu, J. Z., & Qiu, J. J. (2018). Inclined layer printing for fused deposition modeling without assisted supporting structure. *Robotics and Computer-Integrated Manufacturing*, 51, 1-13. https://doi.org/10.1016/j.rcim.2017.11.011
- [12] Dolenc, A. & Mäkelä, I. (1994). Slicing procedures for
- layered manufacturing techniques. *Computer-Aided Design*, 26(2), 119-126. https://doi.org/10.6028/NIST.SP.1176
- [13] Thomas, D. S. & Gilbert, S. W. (2014). Costs and cost effectiveness of additive manufacturing: A Literature review and discussion. NIST.

- [14] Brackett, D., Ashcroft, I., & Hague, R. (2011). Topology optimization for additive manufacturing. In: 22nd Annual international solid freeform fabrication symposium (SFF 2011), 348(62).
- [15] Tournier, C. & Duc, E. (2005). Iso-scallop tool path generation in 5-axis milling. *International Journal of Advanced Manufacturing Technology*, 25(9-10), 867-875. https://doi.org/10.1007/s00170-003-2054-7
- [16] Lee, Y. S. (1998). Non-isoparametric tool path planning by machining strip evaluation for 5-axis sculptured surface machining. *Computer-Aided Design*, 30(7), 559-570. https://doi.org/10.1016/S0010-4485(98)00822-7
- [17] Sun, S. H., Chiang, H. W., & Lee, M. I. (2007). Adaptive direct slicing of a commercial cad model for use in rapid prototyping. *International Journal of Advanced Manufacturing Technology*, 34(7-8), 702-702. https://doi.org/10.1007/s00170-006-0880-0
- [18] Gibson, I., Rosen, D. W., & Stucker, B. (2010). Additive Manufacturing Technologies: Rapid Prototyping to Direct Digital Manufacturing. Springer, US. https://doi.org/10.1007/978-1-4419-1120-9
- [19] Gao, S., Zhao, W., Lin, H., Yang, F., & Chen, X. (2008). Feature suppression based CAD mesh model simplification. *IEEE International Conference on Shape Modeling and Applications, IEEE, Vol.* 42, 1178-1188.
- [20] Chen, X. F. & Zhang, Y. P. (2011). Research about the ways to control the error of FDM forming workpiece. *Modern Manufacturing Engineering*, 31(11), 39-36.
- [21] Zhai, Y., Lados, D. A., & Lagoy, J. L. (2014). Additive manufacturing: making imagination the major limitation. *JOM*, 66(5), 808-816. https://doi.org/10.1007/s11837-014-0886-2
- [22] Rufeng Chen, Zhitong Chen, Wuyi Xianzhen, et al. (2010). Dual drive curve tool path planning method for 5-axis NC machining of sculptured surfaces. *Chinese Journal of Aeronautics*, 23(4), 486-494. https://doi.org/10.1016/S1000-9361(09)60245-4

Contact information:

HaiGuang ZHANG, PhD

Rapid Manufacturing Engineering Center,

Shanghai Key Laboratory of Intelligent Manufacturing and Robotics,

National Demonstration Center for Experimental Engineering Training Education, Shanghai University,

No. 99 Shangda Road, Baoshan district, Shanghai 200072, China haiguang_zhang@i.shu.edu.cn

ZeFeng SUN, PhD student

Rapid Manufacturing Engineering Center,

Shanghai University,

No. 99 Shangda Road, Baoshan district, Shanghai 200444, China 1529789120@qq.com

QingXi HU, Prof. PhD

Corresponding author Rapid Manufacturing Engineering Center,

Shanghai Key Laboratory of Intelligent Manufacturing and Robotics,

National Demonstration Center for Experimental Engineering Training Education, Shanghai University,

No. 99 Shangda Road, Baoshan district, Shanghai 200072, China huqingxi@shu.edu.cn

Herfried LAMMER

Kompetenzzentrum Holz GmbH Altenberger Straße 69, 4040 Linz, Austria h.lammer@kplus-wood.at