

Errata corrigé!

U *Brodogradnji* broj 1/2006 u članku R. Grubišić: „Asphalt Carriers from *Kraljevica Shipyard, Croatia*“ (str. 23-31) na stranici 29 pogrešno je uvrštena tablica **Summary of Loading Conditions**. Na njenom mjestu trebala je biti uvrštena tablica **List of Damage Cases** kako je i naslovljeno. Uz ispriku čitateljima na ovome mjestu objavljujemo korektnu tablicu.

Autor i uredništvo

Author & Editors

In *Brodogradnja* issue 1/2006, in the article written by R. Grubišić: “Asphalt Carriers from *Kraljevica Shipyard, Croatia*” (p. 23-31), on page 29 the table **Summary of Loading Conditions** has been wrongly inserted. Instead of it the table **List of Damage Cases** should have been placed, as written in the table caption. We apologise to the readers for the caused inconvenience and publish the correct table here.

Table 3 **List of damage cases of the final design (*Kraljevica Shipyard*)**
Tablica 3 **Lista slučajeva oštećenja konačnog projekta (*Brodogradilište Kraljevica*)**

LIST OF DAMAGE CASES

DAMAGE CASE No	DAMAGE DESCRIPTION	DAMAGED COMPARTMENTS
1.	Damaged bulkheads Fr.153/158	10 Fore peak, 24 HFO fwd, 12 DBWT (s), No.1 cargo (c), 13WB side (s), Rope store, Bow thrust.sp., Deck/paint store, Coff. arrnd.no.1 cargo tk.
2.	Damaged bulkhead Fr.129	12 DBWBT (s), No.1 cargo tk, 13 WBT Side(s), No 2 cargo tk (c), 14 WB wing (s), Deck/paint store, Coff. arrnd. cargo tks (2-4), Coff.arrnd no 1 cargo tk.
3.	Damaged bulkhead Fr.117	No.2 cargo tk (c), No.3 cargo tk (s) No.14 & No.15 WB wing (s), Coff. arrnd. cargo tks no. 2-4
4.	Damaged bulkhead Fr.97	No.3 cargo tk (s), No.4 cargo tk (c), 15 WB wing (s) 16 WB wing (s), 18 Midship ball. tk (s), Coff. arrnd. cargo tks 2-4
5.	Damaged bulkhead Fr.83	No.4 cargo tk (c), 15 WB wing (s), 16 WB wing (s), 18 Midship ball. tk (s), Coff. arrnd. cargo tks 2-4, Pump room, Cargo residues t (73)
6.	Damaged bulkhead Fr.77/83	No.4 cargo tk (c), No.5 cargo tk (s), 16 WB wing (s), 18 Midship ball.(s), Coff. arrnd cargo tks 2-4, Coff. arrnd cargo tks 5 & 6, Pump room, Cargo residues t (73)
7.	Damaged bulkhead Fr.77	No.5 cargo tk (s), 16 WB wing (s), 17 WB wing (s), Coff. arrnd cargo tks 5 & 6, Pump room, Cargo residues t (73)
8.	Damaged bulkhead Fr.53	No.5 cargo tk (s), No.6 cargo tk (c), 17 WB wing (s), Coff. arrnd cargo tks 5 & 6
9.	Damaged bulkhead Fr.39	No.6 cargo tk (c), 17 WB wing (s), Coff. arrnd cargo tks 5 & 6, HFO No.22
10.	Engine room flooding	Engine room, 20 HFO in ER (s), 26 HFO settl. tk (s), 27 HFO service tk (s), Poop fr. 4-20, Poop fr. 20-32
11.	Damaged aft peak St-12.	19 After peak, Poop (st-fr.4)
12.	Bottom damage at Fr.153/158	10 Fore peak, 24 HFO fwd (s), 11 DBWBT (c), 12 DBWBT (s), Bow thrust. Sp
13.	Bottom damage at Fr.129	11 DBWBT (c), 12 DBWBT (s), Coff. arrnd. cargo tks 2-4
14.	Bottom damage at Fr.77/83	Coff. arrnd. cargo tks 2-4, Coff. arrnd. cargo tks 5 & 6, Pump room, Drip trays drain 71,Pump r.& void bilge 72
15.	Bottom damage at Fr.37/39	Coff. arrnd. Cargo tks 5&6, HFO No.22, HFO No.23, E.R. Bilge 67, Sewage h. 68, M.E. circ.40, Coff. below 40